

XXX 5.40

The sample from the pannier bay doors was also insufficient to identify any OX-87 or other petroleum product. We received some further samples believed to be from the aircraft. The OX-87 sample appears consistent with OX-87 with no evidence of significant contamination. A test report is being prepared.

Regards,

XXX 5.40

XXXX 5.40

XXXX 5.40

QinetiQ

XXX 5.40

XXXX 5.40

Ively Road, Farnborough
Hants, GU14 0LX

Tel: XXXX 5.40

Email: XXXX 5.40

Fax: XXXX 5.40

Web: www.QinetiQ.com

QinetiQ - The Global Defence and Security Experts